

FIG. 1




FIG. 2




FIG. 3




FIG. 4







FIG. 5



1950




FIG. 7





FIG. 8



VIEW A

FIG. 9




FIG. 10

SECTION A-A





FIG. 11



9/16

FIG. 12





FIG. 13



10/16

FIG. 14





FIG. 15

SECTION A-A



11/16

FIG. 16




FIG. 17

VIEW C




FIG. 18

VIEW B






FIG. 19



700



TOP
SUPPORT
PLATE




FIG. 22





FIG. 23



15/16

FIG. 24

VIEW A




FIG. 25




FIG. 26

